

BUILDING SAFETY CERTIFICATE

No. 408


Dated: 26/04/2024

Certified that the existing building **Guru Brahmanand Sr. Sec. School** at **Assandh Road, VPO. Untla, Tehsil. Madlauda, Near Thermal Power Station, Panipat, Haryana** comprised of **without** basement(s) and **Total 3 Blocks** out of which **Block 1- with Ground Floor**, and **Block 2- with Ground Floor + First Floor**, and **Block 3-with Ground Floor + First Floor + Second Floor** occupied by **Guru Brahmanand Sr. Sec. School** have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **PWD (B&R) Haryana** on **24.04.2024**(date of inspection) in the presence of **Mr. Pawan Kumar (Director) Guru Brahmanand Sr. Sec. School** (**H.no.89/2, Krishan Pura, Panipat**) and that the building/premises is fit for occupancy upto classes XII with effect from **24.04.2024** for a period of **FIVE** years in accordance with rule and subject to compliance of the specific conditions as appended.

1. As per latest National Building code Rules/amendments from time to time.

Issued on **26.04.2024** at **Panipat** by

* Strike out whichever is not applicable.


Sub Divisional Engineer
Provincial Sub Division No.-I
Signature with Seal **PWD B&R Br., Panipat**

Name : Rambal Singh

Designation : Sub Division Engineer

Name & Address of Department/ Office: PWD (B&R), Panipat

(Assistant Engineer & above officer of concerned Govt. Department only)